


Zortman Mine Reclamation Progress


- **Reclamation Includes:**
 - Backfilling
 - Regrading
 - Barrier Installation
 - Soil Placement
 - Revegetation
 - Maintenance
- **Some Reclamation done by ZMI prior to 1998**
- **Interim Reclamation began in 1999 by DEQ and BLM after site abandonment by ZMI**

Zortman and Landusky Mines - Facilities & Land Status Map



Zortman Mine – Facilities & Land Status

OK/Ruby Pit Reclamation





Zortman Mine, OK-Ruby Pit – July 2000



OK-Ruby Pit Backfilling to Cover Sulfides

2001 5 2



**Capping Backfill on OK-Ruby Pit to Limit
Infiltration and Acid Drainage Formation**

2001 11 14

November 2001





**Placing Topsoil on OK-Ruby
Pit Capped Backfill**

2002 4 16



Regraded Zortman Pit Area and Leach Pad

2003 5 14



July 2000




July 2005

Zortman Mine - OK/Ruby Pit Reclamation

July 2000 to July 2005



Leach Pad Reclamation





May 1991- Regraded Z79-80 Leach pads. Active Z89 Leach pad on right



November 2001 - Reclaimed Z79-80 Leach pads. Regraded Z89 Leach pad on right



2004 9 22

Reclamation of the Z79-80 and Z89 Leach Pads

1991 to 2004



**May 1991. Z79-80 Leach pads.
Active Z89 leach pad to the right**

Sept. 2004 - Reclaimed Z79-80, and Z89 leach pads.



Zortman Mine - July 2000



Zortman Mine – July 2005



Zortman Mine Reclamation

July 2000 to July 2005



July 2000



July 2005

Zortman Mine - June 1993



Zortman Mine - July 2005



Zortman Mine Reclamation 1993 to 2005



June 1993 – At Full Buildout

July 2005 – Reclamation Complete

